


Engine draining in exhaust stub retrofit

Enjoy the latest enhancement for your TBM




Engine draining in exhaust stub

Collection of the engine drains towards the R.H exhaust stub to avoid Oxygen bottle area contamination hazard, burning oil in the exhaust.

Validity
SN 1 to 204, 206 to 215

SB Reference

SB70-097-71



Applicable Not applicable Already applied

Reference to order

OPT70K08071

Estimated labor hours

10 hours labor