

## Exhaust stacks retrofit

Enjoy the latest enhancement for your TBM



### Exhaust stacks

Replacement of the RH and LH exhaust stacks by “Generation 2” exhausts which will significantly reduce the soot built-up without any performance alteration.

It is strongly recommended to include the Oil drainage kit in addition to this modification.

That will avoid the presence of oily dirt on the lower fuselage skin

#### Validity


SN 346 to 570 equipped with MOD70-0202-78 or with OPT70K111-78

#### Reference to order

T700F781000500700 (R.H)  
T700F781000500600 (L.H)

#### Estimated labor hours

6 hours labor



Applicable Not applicable Already applied